



TOP VIEW





SECTION LOOKING NORTH



SECTION LOOKING SOUTH

- NEW ART INSTALLATION - "SKILLETS"





SECTION LOOKING WEST



SECTION LOOKING EAST








ELEVATION LOOKING SOUTH

3/16" = 1'-0"




ELEVATION LOOKING WEST

PAINT - SHERWIN WILLIAMS
SW 7069 'IRON ORE'

PAINT - SHERWIN WILLIAMS
SW 7005 'PURE WHITE'


SIDE WALL

3/16" = 1'-0"



SIDE DOOR VESTIBULE


3/16" = 1'-0"




RESTROOM/DISHPIT VESTIBULE

3/16" = 1'-0"







BACKBAR - ELEVATIONS










MEN'S RESTROOM











WOMEN'S RESTROOM



FLOOR PLAN @ SIDE ROOM




SLIDING DOORS - CLOSED




SLIDING DOORS - OPEN



SLIDING DOOR @ BENCH







BUILDING ELEVATION - E UNION ST (EXIST)

1/8" = 1'-0"



NOTE: ALL DIMENSIONS to be VERIFIED in FIELD

BUILDING ELEVATION - 14th AVE (EXIST)


















SKILLET DINER - EXISTING PATIO







PATIO from NW



PATIO from SE



PATIO ELEVATION - E UNION ST


1/8" = 1'-0"



PATIO ELEVATION - 14th AVE


NOTE: ALL DIMENSIONS to be VERIFIED in FIELD

ALTERNATIVE END CONDITION: INTEGRAL GUTTER w/in STRUCTURAL BEAM (NO OVERHANG) SEE PHOTOS of 'EUREKA BURGER' PATIO




PATIO ENCLOSURE ELEVATION - E UNION ST


1/8" = 1'-0"



PATIO ENCLOSURE ELEVATION - 14th AVE

NOTE: ALL DIMENSIONS to be VERIFIED in FIELD





UPPER PATIO - FLOOR PLAN

UPPER PATIO - CLG ELEMENTS + POWER



UPPER PATIO from NE

ELECTRIC HEATERS MOUNTED to UNDERSIDE of CEILING



UPPER PATIO from SE



UPPER PATIO from SW



UPPER PATIO - BACKWALL ELEVATION