



Whatcom County
HEALTH
Department



Whatcom County
On-site Sewage System
(OSS)
Report Of System Status

509 Girard St
Bellingham WA 98225
360 778 6000

Site		Evaluation	
Site Address	8085 AUDRA LN	Evaluation Date	a8289742 7/22/2025
Parcel (first 12 digits)	400230138422	OM Specialist	Nate Macy
Property ID	177302	Customer Name	JERRY CRABTREE
OSS SiteID	18226	Customer Phone	360-000-0001
OSS Site Description		Performed For	Routine Compliance
Scanned OSS Doc	Yes	Sewage Source	Single Family
OSS Type	Gravity	Bedrooms Served	2
Proprietary Treatment Product	No	Certified to perform maintenance for this proprietary product	
Sand Filter	No		

Results

Op Status On Arrival	Satisfactory
Maintenance Performed--Pumping	No
Maintenance Performed	
Op Status On Completion	Satisfactory
Maintenance Needed--Pumping	No
Maintenance Needed Item 1	
Maintenance Needed Item 2	
Maintenance Needed Item 3	

General Comments

This report is a snapshot of the system condition at the time of inspection only. Septic Plus, Inc and/or its inspectors do not warrant or guarantee the future condition of this septic system. Proper & timely maintenance and inspection is key in helping promote the long-term health of the septic system.

O&M Specialist

Nate Macy

7/25/2025 2:45:02 PM

Septic Tank

Septic Tank Watertight	Yes
Septic Tank Scum Depth at Inlet (inches)	3.00
Septic Tank Sludge Depth at Inlet (inches)	3.00
Septic Tank Sludge Depth at Outlet (inches)	2.00
Septic Tank Scum Depth at Outlet (inches)	0.00
Septic Tank Pumping Required	No, pumping not required
Septic Tank Inlet baffle condition	Satisfactory
Septic Tank Outlet baffle condition	Satisfactory
Septic Tank Outlet filter	Not present
Outlet filter cleaned	
Septic Tank Condition of Risers	Not present
Septic Tank Condition of Lid:	Satisfactory
Septic Tank Lids Secured	Yes
Septic Tank Comments	

Second Septic Tank? No

Pump Tank No

Second Pump Tank?

Proprietary Treatment Product (PTP) No

Sand Filter (SF) No

Drip (SDS)

Drainfield

Surface water/downspouts diverted away from drainfield	Yes
Improper encroachment (structures/impervious surfaces)	No
Structural Integrity and Vegetative Cover Properly Managed	Yes
Ponding, Seepage, or Saturation near/around Drainfield	No
Describe Ponding, Seepage, Saturation	
Monitoring Ports Condition	N/A
Is sewage ponding in ports	
Effluent at same level in all basins	
Distribution Box (surface access)	N/A
Distribution Box Condition	
Equal Distribution	
Diversion Valve present/functioning	
Laterals flushed - Drainfield	
Squirt Height At Distal End (inches)	
Orifice Size Used (inches)	
Equal Distribution - Drainfield	
Length Of Flow Test (minutes)	20.00
Approximate Gallons	120

Level In Septic Tank At Start Of Test	Normal(invert of outlet baffle)
Level At End Of Test	Normal(invert of outlet baffle)
Pump Systems - Float Tether Length (inches)	
Number Of Pump Cycles Run	
Gallons Pumped During Test	
Evidence Of Dye Or Effluent Surfacing	No
Color Of Dye Used	Green

8085 AUDRA LN (400230138422) Site-18226 Eval-a8289742 on 07/22/2025



Photo - Misc: Septic Tank



Photo - Misc2: Drainfield

{ End of Report - 8085 AUDRA LN (400230138422) Site-18226 Eval-a8289742 on 07/22/2025 }